



Engineered Core veneer (ECV)

MATERIAL SAFETY DATA SHEET NO.001



IDENTIFICATION

Product Name: ENGINEERED CORE VENEER (ECV)

UN Number: None allocated.
Dangerous Goods Class: None allocated.
Hazchem Code: None allocated.
Toxic Substances Schedule: Not scheduled
Uses: Construction of furniture, cabinets and doors. General purpose building and packaging for high value items.
Appearance: Patinna products are manufactured as compressed wood panel sheets in thickness from 1.6mm to 36mm. They are made from wood fibres bonded together with formaldehyde-based resins. This density of products range from 380 to 940 kg/m³ and are referred to as medium density fibreboards (MDF).
Boiling Point (°C): Not applicable
Vapour Pressure (mm Hg at 25 °C): Not applicable
Vapour Density: Not applicable
Solubility in Water (g/l): Not soluble
Specific Gravity (relative to water): 0.4-0.9
Flash Point (°C): Not applicable
Flammability Limits (%): Not available
Odour: Newly manufactured board, and freshly cut surfaces may have an odour due to residual formaldehyde from the resin binder.

INGREDIENTS:

<i>Chemical Entity</i>	<i>Cas No.</i>	<i>Proportion</i>
Plantation softwoods	None	>80 %
Urea/melamine/Phenol formaldehyde resins	9011-05-6 9003-35-4	<21%
Paraffin wax	8002-74-2	<1%

Note: The above ingredients are bound together under heat and pressure. The cured resin may release small amounts of formaldehyde from the finished product. The finished product contains less than 0.1% free formaldehyde.



HEALTH HAZARD INFORMATION

Health Effects: When first manufactured, the unsealed surfaces of these boards may release small quantities of formaldehyde gas. The concentrations will be highest when the boards are stored in confined, poorly ventilated spaces. When the boards are sealed with paint, varnish, or other surface decorative finishes, the potential for the release of formaldehyde will be greatly reduced. When the boards are cut, drilled or sanded etc. dust will be given off.

The known health effects of the constituents of the boards are as follows:

Wood Dust: Dust and splinters may cause irritation of the nose and throat, eyes and skin. Some woods may also be sensitizers, and some people may develop allergic dermatitis or asthma. Inhalation of wood dust, both hardwood and softwood, may increase the risk of nasal and paranasal cancers. The International Agency for Research on Cancer (IARC), in 1995 classed wood dust as carcinogenic to humans.

Cured Resin: The cured resin is inert, and not likely to contribute to health effects.

Paraffin Wax: The wax vapour may be irritating to the nose and throat, eyes and skin, if the board is heated to 120 °C or more.

Formaldehyde: Formaldehyde gas and dilute solutions of formaldehyde in water are irritating to the nose and throat, eyes and skin. The solutions are also sensitizers and contact dermatitis has been reported.

The International Agency for Research on Cancer (IARC), reassessed the hazard classification of formaldehyde in June 2004 and upgraded from Group 2A to Group 1 which means it is now considered carcinogenic to humans. This is the same hazard classification as wood dust. The reclassification was based on new information from epidemiology studies which provided evidence that workers exposed to high levels of formaldehyde in the workplace are at risk from developing nasopharyngeal cancer. The reclassification has still to be officially published and so workplace standards still reflect the old classification.

Exposure to the dust, gas and vapour from the boards may result in the following health effects:

Acute Effects:

Swallowed: Unlikely to occur, but swallowing would result in abdominal discomfort.

Eye: The dust, gas and vapour may be irritating to the eyes causing discomfort and redness.

Skin: The dust, gas and vapour may irritate the skin, resulting in itching, and occasionally a red rash. Allergic dermatitis may occur.

Inhaled: The dust, gas and vapour may irritate the nose, throat and lungs; especially in people with upper respiratory tract or chest complaints. Asthma may occur.

Chronic Effects:

Repeated exposure over many years to uncontrolled dusts from these boards may result in allergic dermatitis, asthma, or chronic nose or throat irritation in some people. The risk of nasal or paranasal sinus cancers may be increased. But if the work practices noted in the MSDS are followed, and exposure to airborne dust is kept to low, no chronic health effects are anticipated.

First Aid:

Swallowed: Drink a glass of water.

Eye: Flush with running water for at least 15 minutes, and if symptoms persist seek immediate medical attention.

Skin: Wash with mild soap and water.

Inhaled: Leave the dusty area.

Advice to Doctor: Treat symptomatically.